

COC 8 COC Starting Projector COC



🔵 🔿 OSD Lite Menu 🔾



	Toggle between input sources
BRIGHTNESS	adjust lamp brightness level
CONTRAST	adjust image contrast
	adjust image colour
ASPECT RATIO	modify image aspect ratio
LENS FOCUS	adjust lens focus
LENS ZOOM	adjust lens zoom
LENS SHIFT	adjust lens shift
	adjust keystone
LANGUAGE	select language
INFO	information on lamp status
MODE	normal/eco/power
SERVICE	service information
ADVANCED	see user manual

)10()()() Important Info()()())(

- Remove the lens before transporting the projector.
- To save lamp lifetime, first switch the projector to standby mode
- and wait two minutes, then switch off the main power.
- Ensure that the projector is operating with clean filters.
- Do not block the ventilation in -and outlets.
- Using the projector at a non recommended tilt angle will reduce the lifetime of the lamps or create unexpected behaviour of the unit.
- Laser light can cause severe damage to the DMD. This damage is not covered by warranty.



For more information and Maintenance Guidelines, check the Detailed User Manual on: http://www.barco.com/en/products-solutions/projectors